

Neighbourhood Infrastructure Improvement Fund


Appendix 1

Template for Ideas Gathering

Name of Area Partnership: Maryhill

Description of work required for Estimate - Please provide as detailed a description as possible including type of work required, number and type of items required/special considerations or known issues etc	Location of Work required for Estimate - Please provide a detailed description of the EXACT location (Street Name & Extents) of work required:
CENTRAL MARYHILL	
No lights working to light up the archway. New lights to be put up total of 6. Known issues are residents are frightened to walk to their homes at night.	Orangate archways through to other properties
Paving stones/slabs, issues are they are loose or broken and a danger to the public and disabled, and wheelchair users. Slabs and Paving have to be replaced or fixed.	Wyndford drive & road, Glenfinnan Rd, & drive Garbrald Place, Fogo Place and Road. The full paths must all be redone or replaced with something else.
Set of traffic lights and speed bumps to be put in place as the road has no crossing for the residents to cross safely and cars drive too fast around the corners.	Kelvindale road, 1 set of traffic lights at the back entrance of the new health centre. Also speed bumps to be put in place to slow the traffic down coming out of local streets.
Main road flooding at bottom of stairs coming from the Wyndford estate down to the main road.	Kelvindale road, more drainage must be put in place to help with the large puddle that ends up covering the full road across to the entrance of the health centre. And the road needs to be raised to stop this happening.
Walkways on both sides of the road under also not wide enough for residents to walk on or wheelchair users to be able use.	Maryhill Bridge pavements must be wider for disabled wheelchair users to get under the bridge.
New bin rooms to put in place. Due to bins being put in the open and causing rats, and also rats getting into people's homes.	The full length of Hathaway Lane.
All roads in the Wyndford estate.	Speed bumps are required as cars driving too fast in a built-up area with families with

	young children, and also local nursery just off the main road.
Hazarded to the publics safety overgrown trees falling onto main walkways and gardens.	The trees are overgrown and can cause residents to slip. And there are some trees that are dead and need removed in the following streets, Carrbridge drive ,Latherton Drive, Invershin drive, and Glenfinnan road. These need to be cut back and dead trees removed
Lights on the main path from the entrance of the Wyndford estate	The pathway is to dark in winter and at night. We must have more at least about 5 extra lights put in place as it's a danger at night in this part of the Wyndford.
Wyndford nursery and at the back of the G20 youth centre is a must for more lights to be put in place.	More lights put on pathway at least 6 so that the full area is lite up at night. And also, CCTV put in place behind the G20 youth group and the local shop at Wyndford Road.
Stairways	At the end of carrbridge drive going down to Kelvindale road, the stairs are all damaged and a danger to anyone using them.
Parking for car owners and Disabled spaces	We need more parking to be made available for drivers. So that there are cars on walkways there is a large part of grass area just off Wyndford Rd that could be made into a large carpark.
Entrance to houses	Lights have to be put up in the following area 80-108 Wyndford road. Due to being a small pathway and at dark nights it is pitch black and also a danger to the public. We need at least 6 lights to fitted along this pathway.
All stairways Handrails need to be replaced or fixed.	The Wyndford Nursery has three stairways that have broken steps and hand rails need replaced This is at Ardesie Place.
Speed bumps known issues are boy racers	Kelvindale road, Guthrie street and Balfore street. These roads are in a built-up area with children crossing roads.

CCTV, special considerations are this is housing for disabled and pensioner's	Kelvindale road This housing area is a must for CCTV as its vulnerable residents that live in these houses.
NORTH MARYHILL, ACRE AND SUMMERSTON	
Acre	<p>Acre Footpath Improvements Repairs to broken slabs and footpath - SB advised this was raised in Nov 23 and April 24, please see SB's email 10/02/2025 confirming discussion.</p> <p>Question – does this work still fit within the NIIF criteria?</p> 
	Traffic Calming – Chicanes
	<p>Acre Road/Drive</p> <p>Streetscape improvements – Rockery/plants features, and permanent welcome signs into the areas</p> <p>Throughout Acre and possibly the rest of the Ward</p>
	<p>https://images.app.goo.gl/94Wi1GGMKPEvLeMP7 https://images.app.goo.gl/BnUZD8t2HMPNK4Ac8</p>
	<p>Improvements to dangerous stairs</p> <p>Acre Road</p>
S'ton	<p>Summerston – Improvement public space “the triangle” Proposal submitted – Oct 2023. Improve a public space adjacent to St Blanes Primary School and a ‘cut thru’ area in the centre of Summerston.</p>
	<p>Summerston – a fenced and accessible dog run Proposal submitted – Oct 2023. Repurpose public space to divert dog owners away from MUGGA and promote responsible dog ownership/socialising.</p> <p>Location to be identified by GCC, still pending Suggestions from the community include</p> <ul style="list-style-type: none"> • behind bus terminus • Maryhill Park • old allotments between the Meadows and Torrin Road • green space opposite Caldercuilt School at Balmartin Road and Harris Road. • Adjacent to the MUGGA off Craigbo Road.
	<p>Improvement to Children’s Play Area – fix and paint railings, extend</p> <p>adjacent to John Paul Academy off Arrochar St / Geary Street</p>

	play area/equipment / improve landscaping.	
G'hill	CCTV camera To combat fly tipping in identified hot spot. Noted in mins of August 2022 with specific suggestions recorded in Jan 2023 mins (including suggestions from SCEG)	Location: Lyndale Road and Kilmun Street - <i>this has been approved but there was issue with installation?</i>
	Other issues MHA raised issues for parts of central Maryhill and NMASCC also raised issues to do with broken stairs, tree roots and leaks.	<ul style="list-style-type: none"> • Repair stairs behind the Sportsman Bar (between this pub and the Kelvin Dock) • Fencing beside Play area • Leaning wall / slabbed area needs repaired. •
	Pelican crossing	Shiskine Drive
M/Park	CCTV Camera – Maryhill Park	NMASCC have no info on this
	Maryhill Graveyard Additional funds to the Maryhill Graveyard due to increased costs to complete the work, presented directly to Area Partnership by GCC Parks team.	Approved by Area Partnership - £10,000
	Outdoor Gym Equipment	Maryhill Park
	Improvements to facilities and existing areas at Maryhill Park – picnic areas, more play equipment for older children, public vote on park improvements	Maryhill Park
Boundary wide	St Blanes Primary School and St Mary's Primary School fences	St Blanes – led testing is clear – NRS have advised this will be done in spring 2025, weather permitting. St Mary's – led testing positive – specialist company required to complete the work, NRS to provide update
	Pitch Improvements at both St Blanes & St Mary's School Pitches.	NMASCC have no info on this?

	Public seating	Throughout the Ward
	Appropriate Murals aligned to Maryhill's past	Maryhill Road
	Reinstate the running track / pitches	Jordanhill sports Ground / Maryhill Park
	Improved flower meadows / raised beds	Across the neighbourhood.
	Improved kerb appeal of community buildings	Bellcraig CC Ledgowan Hall

The maps below outline NMASSC boundary and then a suggestion that there are 4 sub-divisions that make up NMASSC area.

1. Acre
2. Summerston
3. Maryhill Park / Road
4. Gillshochill.

This will allow us to consider the funds split into smaller pots but ensuring the full ward gain from the NIIF investment. With a 5th category of boundary wide.

