

Neighbourhood Infrastructure Improvement Fund

Appendix 1

Template for Ideas Gathering**Name of Area Partnership: Partick East Kelvindale Area Partnership**

Description of work required for Estimate - Please provide as detailed a description as possible including type of work required, number and type of items required/special considerations or known issues etc	Location of Work required for Estimate - Please provide a detailed description of the EXACT location (Street Name & Extents) of work required:
Resurfacing of the section of Hyndland Road between Novar Drive and Queensborough Gardens. Much of Hyndland Road has been recently resurfaced but this bit has been left out and needs it now.	Hyndland Road between Novar Drive and Queensborough Gardens.
Resurfacing of Clarence Drive from Hyndland Road to the Railway bridge just beyond number 105 Clarence Drive. The south side of the road (beside the school and the shops) is worse, so if needed the resurfacing could be restricted to the south (school) side.	Clarence Drive from Hyndland Road to the Railway bridge just beyond number 105 Clarence Drive.