Ward 23 - Area Partnership - Infrastructure Fund
Hyndland Railings Survey - Map and List of Repair Issues

January 2024 - Dowanhill, Hyndland and Kelvinside Community Council

NOTE: Colour Of All Railings: BLACK In Keeping With Glasgow West Conservation Area

MISSING SECTION OF RAILING

Airlie Street, at Hyndland Secondary School (location 8)

OTHER TYPES OF DAMAGE TO RAILINGS

KEY B - **Bent** in a parallel collision with vehicle
L - **Leaning backwards,** eg by Bin Lorry

Queensborough Gardens (north side)

1 At Novar Lane B
2 At Airlie Lane LL
3 At Polwarth Lane L
4 At Lauderdale Lane L
5 At Falkland Lane L and section broken off

Lauderdale Gardens between Queensborough and Clarence Drive


6 Both sections BB BB B

Dudley Drive

7 Both sections between Clarence Dr and Turnberry Road BBBB (and a short section not black)

Airlie Street

8 Section at Hyndland Secondary, BBB, Broken Gate (also section missing, see above)



KEY

Boundary of Hyndland Tenements within Glasgow West Conservation Area

B or BB	Railings Bent (vehicle collision)
MISSING	Entire section has been lost
L or LL	Section leaning back over grass (bin lorries going in/out of lane?)