## Template for Ideas Gathering

## Name of Area Partnership: EAST CENTRE WARD 18

Description of work required for	Location of Work required for Cationata
Description of work required for	Location of Work required for Estimate -
Estimate -	Please provide a detailed description of the
Please provide as detailed a description	EXACT location (Street Name & Extents) of
as possible including type of work	work required:
required, number and type of items	
required/special considerations or	
known issues etc	
PLAYPARKS AND PARKS	
Assessment on play equipment already	Playpark – Strone Road – Strone Road Play Area
there and possibly a shelter.	- Strone Road East
Walkway within the park	Cranhill Park - 7 Gantock Crescent
65th Anniversary 2025 – can an item be	Cranhill Park
placed in the park to commemorate this?	
What is required – Suggestions?	Green space between Strone Road and Cranhill
	Primary School – possibly between Langness
	Road and Monarch Road
Assessment on Equipment and Repair or	Kerrera Road – Barlanark Park – Small Swing
Replace and possibly new additional	Park
equipment.	
Repairs to the Barlanark MUGA.	
LANES AND WALKWAYS	
Barrier at Skerryvore Road at the foot of	Lane in between Skerryvore Road and Bellrock
the lane and a handrail going down the	Street
lane.	
Maintenance of Trees and overgrown	High flats at Fastnet Street/ Cloch Street
bushes blocking the walking path, more	
lighting and Salt Bins required.	
Repair or replace steps going down at	Identify exactly where?
Greenfield	
Benches that are already there need	Budhill Square – Crammond Terrace
painted and some new flower troughs in	
the gardens and some maintenance	
done on the overgrown trees and	
bushes.	
New the benches under the trees	Budhill Avenue at Budhill Square
TRAFFIC SIGNALS/CROSSINGS AND	
TRAFFIC SIGNAGE	
One Way Traffic System?	Gantock Crescent or Crowlin Crescent
Resurface Road – too many potholes	Gantock Crescent
Zebra or Pedestrian Crossing.	Eskbank Street – Duror Street – Greenfield
	Football Centre Entrance
Traffic Signage – Reduce Speed	Hallhill Road/South Hallhill Road
Pedestrian Crossing already there outside	South Hallhill Road
Aldi?	
Speed Bumps	Hollowglen Road

Traffic Signage – Reduce Speed	Torphin Walk leading onto Torphin Crescent
Replace or Repair Steps	Pendeen Road (Ward 18) East Centre – Steps
	going down onto Glenduffhill Road
CCTV'S	
Flytipping on Spare Ground outside the	Inverleith Street/Muiryfauld Road
church	
MURALS	
6 Murals across Ward 18	Riddrie, Cranhill, Carntyne, Barlanark,
	Greenfield and Springboig
DEMOLITION	
Demolition of the toilets	Carntyne Square